



Overview: Part of the spill impact on 6" Obigbo – North Pipeline route at Ogale. Picture was taken during Joint Investigation of 20th October, 2011.



Close-up: Hacksaw cut on 6" Obigbo – North Pipeline at Ogale. Picture was taken during Joint Investigation of 20th October, 2011.