



Close-up: Illegal fitting on 8" Nkali-Imo River2 pipeline at Odagwa. Picture was taken during Joint Investigation of 21st November, 2011.