



Overview: Spill due to multiple drilled holes on 24" Alakiri-Bonny pipeline right of way at Ilomaturu. Picture taken during Joint Investigation of 8th October, 2011.



Close-up: Drilled hole on 24" Alakiri-Bonny pipeline right of way at Ilomaturu. Picture taken during Joint Investigation of 8th October, 2011.