



Overview: Part of spill impact on 28" Awoba-Cawthorne Channel pipeline right of way at Brigede. Picture was taken during Joint Investigation of 27<sup>th</sup> October 2011.



Close up: Spill point at 6 'o clock position on 28" Awoba-Cawthorne Channel pipeline right of way at Brigede. Picture was taken during Joint Investigation of 24<sup>th</sup> February 2012.