



Close-up: Hack saw cut on 6" Obigbo – North Pipeline at Ogale. Picture was taken during Joint Investigation of 20th October 2011.