



Overview: Part of spill impact on 28" Nkpoku-Bomu pipeline right of way at Aleto. Picture was taken during Joint Investigation of 26th October 2012.



Close up: Illegal fittings on 28" Nkpoku-Bomu pipeline at Aleto. Picture was taken during Joint Investigation of 26th October 2012.