



Overview: Burning crude theft supertanker on 28" Bomu-Bonny Tran Niger pipeline right of way at Okolo. Picture was taken during overfly of 30th September 2012.



Overview: Part of spill impact on 28" Bomu-Bonny Tran Niger pipeline right of way at Okolo. Picture was taken during Joint Investigation of 6th October 2012.



Close up: Illegal fittings on 28" Bomu-Bonny Tran Niger pipeline at Okolo. Picture was taken during Joint Investigation of 15th October 2012.



Close up: Illegal fittings on 28" Bomu-Bonny Tran Niger pipeline at Okolo. Picture was taken during Joint Investigation of 20th October 2012.