


Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline at Kporghor-Ekporo-Gbam. Picture was taken during Joint Investigation of 10th October 2016.



Close-up: Leaking Illegal fitting on 28" Nkpoku-Bomu Pipeline at Kporghor-Ekporo-Gbam. Picture was taken during Joint Investigation of 10th October 2016.