




Overview: Part of spill impact on Agbada 1 Well 13 and 18 Wellheads at Omunike. Picture was taken during Joint Investigation of 13<sup>th</sup> October 2016.



Close-up: Vandalized Wellhead and Disconnected Flowline on Agbada 1 Well 13 and 18 Wellheads at Omunike. Picture was taken during Joint Investigation of 13<sup>th</sup> October 2016.