



**Overview:** Parts of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Gio.  
 Picture was taken during Joint Investigation of 11th October 2018.



**Close up:** Drilled Holes on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 11th October 2018.