



Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Okpa-Umuakpahu. Picture was taken during Joint Investigation of 3rd October 2018.



Close up: Illegal fittings on 12" Imo River – Ogale Pipeline at Okpa-Umuakpahu. Picture was taken Joint Investigation of 3rd October 2018.