



Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline at Imogu-Rumuekpe. Picture was taken during Joint Investigation of 19th October 2018.



Close up: Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Imogu-Rumuekpe. Picture was taken during Joint Investigation of 19th October 2018.