



Overview: Part of spill impact on 4" Bonny Well 18S Flowline Riser at Oloma. Picture was taken during Joint Investigation of 31st October 2018.



Close up: Impacted Section on 4" Bonny Well 18S Flowline Riser at Oloma. Picture was taken during Joint Investigation of 31st October 2018.