



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 29th October 2018.



Close up: Illegal fitting on 24" Bomu-Bonny Pipeline at Patrick Waterside. Picture was taken during Joint Investigation of 2nd November 2018.