




Overview: Part of spill impact on 18" Soku – Buguma Pipeline Right of Way at Soku. Picture was taken during Joint Investigation of 11th February 2019.



Close-up: Illegal fitting on 18" Soku – Buguma Pipeline at Soku. Picture was taken during Joint Investigation of 11th February 2019.