


Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ihuowo. Picture was taken during Joint Investigation of 12th October 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ihuowo. Picture was taken during Joint Investigation of 12th October 2019.