




**Overview:** Part of spill impact on 12inch Imo River2 – Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 18<sup>th</sup> October 2019.



**Close-up:** Illegal fitting on 12inch Imo River2 – Ogale Pipeline at Ogale. Picture was taken during Joint Investigation of 18<sup>th</sup> October 2019.