




Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ikarama
 Picture was taken during Joint Investigation of 9th October 2019.



Close-up: Hack Saw Cut on 14" Okordia - Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 9th October 2019.