



Overview: Part of spill impact on 4" Agbada2 Well 58 Flowline at Omueke. Picture was taken during Joint Investigation of 30th October 2019.



Close-up: Hack Saw Cuts on 4" Agbada2 Well 58 Flowline at Omueke. Picture was taken during Joint Investigation of 30th October 2019.



Close-up: Hack Saw Cuts on 4" Agbada2 Well 58 Flowline at Omueke. Picture was taken during Joint Investigation of 30th October 2019.