




Overview: Part of spill impact on 24" Bomu – Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 31st October 2019.



Close-up: Illegal fitting on 24" Bomu – Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 31st October 2019.