



		E 7.151346	Date 2019/11/12
		N 4.796889	Time 14:12:19 +01:00
		Altitude 26.400 M	Speed 0.00 KPH

**Overview:** Part of spill impact on 12'' Imo River – Ogale Pipeline Right of Way at Obolo  
 Picture was taken during Joint Investigation of 12<sup>th</sup> November 2019.



		E 7.151351	Date 2019/11/17
		N 4.796876	Time 15:40:12 +01:00
		Altitude 22.000 M	Speed 0.07 KPH

**Close-up:** Illegal fittings on 12'' Imo River – Ogale Pipeline at Obolo . Picture was taken during  
 Joint Investigation of 17<sup>th</sup> November 2019.