



Overview: Part of spill incident impact at 20" Kolocreek–Rumuekpe Pipeline right of way at Ogbogolo. Picture was taken during JIV of 23rd September, 2011



Close-up: Spill due to failed dam on 20" Kolocreek–Rumuekpe Pipeline at Ogbogolo. Picture was taken during JIV of 23rd September, 2011