



Overview: Part of spill impact on 20" Otumara-Escravos pipeline right of way at Ugborodo/Ugboegungun. Picture was taken during Joint Investigation of 11th September 2013.



Close up: Illegal fitting 20" Otumara-Escravos pipeline at Ugborodo/Ugboegungun. Picture was taken during Joint Investigation of 11th September 2013.



Close up: Illegal fitting on 20" Otumara-Escravos pipeline at Ugborodo/Ugboegungun.
Picture was taken during Joint Investigation of 11th September 2013.