



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline Right of Way at Owokiri. Picture was taken during Joint Investigation of 7th October 2015.



Close-up: Spill due to corrosion on 24" Bomu-Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation of 7th October 2015.