




Overview: Part of spill impact on 24" Nkpoku - Bomu Pipeline at Agbeta. Picture was taken during Joint Investigation on 2nd September 2020.



Close-up: Position of missing Clamp and drilled hole at 12 o'clock position on 24" Nkpoku - Bomu Pipeline at Agbeta. Picture was taken during Joint Investigation on 2nd September 2020.