


Overview: Part of spill impact on 12" Imo River 2 – Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation on 5th September 2020.



Close-up: 2 nos crude oil theft points at 12 o'clock position on 12" Imo River 2 – Ogale Pipeline at Odagwa. Picture was taken during Joint Investigation on 5th September 2020.