



Overview: Part of spill impact on 12" Imo River2 - Ogale Pipeline at Umuololo. Picture was taken during Joint Investigation on 9th September 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 12" Imo River2 - Ogale Pipeline at Umuololo. Picture was taken during Joint Investigation on 9th September 2020.