



Overview: Part of spill impact on Ubie Flow Station at Idu-Ekpeye . Picture was taken during Joint Investigation on 17th September 2020.



Close-up: Overflow Saver pit on Ubie Flow Station at Idu-Ekpeye . Picture was taken during Joint Investigation on 17th September 2020.